

COLD BAY AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location: Near the south end of the Alaska Peninsula
- District: Southwest
- Airport Manager: Jerry Diaz
- District Maintenance Manager: Andy Peterson
- Pavement Surface: Hot recycled Asphalt Concrete, Asphalt Concrete, some with slurry seal or tar seal
- Last Pavement Construction: 1989
- Pavement layout: Runways 14-32, 8-26, three taxiways and two aprons
- Design Aircraft: B-747-400
- 2000 Enplanements: 8,016
- Airport Class: Non-Primary
- Last pavement condition survey: Sept. 2002
- Next planned pavement condition survey: 2005
- 2001 reported pavement maintenance and/or changed conditions: Rehabilitation of R/W 8-26, T/Ws A & B and the South Apron are in Design
- Recommendations: See PCI maps